

PIXERA MEDIA SERVER CAPTURE CARDS LATENCY

Input

The following table provides an overview of the latency from capture to output.

Capture Cards	Input	Delay in Frames
PXO-IH2	2x HDMI 2.0	3 frames
PXO-CT2H1	1x 12G-SDI/4x 3G-SDI	2 frames
	1x HDMI 2.0	3 frames
PXO-IS2	2x 3G-SDI	2 frames
PXO-IS4	4x 3G-SDI	3 frames
PXO-CS4	4x 3G-SDI	3 frames
PXO-CS8	8x 3G-SDI	3 frames
PXO-CT4	4x 12G-SDI/8x 3G-SDI	3 frames
PXO-IS1	1x 3G SDI	2 frames

